(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

REFERENCE: BLUE SPRINGS

ATTACHMENT TO L-2885 15 MARCH 1967 PAGE 1

PETROLEUM PRODUCTS STORAGE HAI PHONG, NORTH VIETNAM 2052N 10639E

(SEE NPIC BRIEFING BOARD L-1461 FOR COMPARISON)

1. SIGNIFICANCE:

X1

5X1

5X1

THIS BRIEFING BOARD DEPICTS STRIKE DAMAGE TO THE HAI PHONG PETROLEUM PRODUCTS STORAGE.

2. LOCATION:

THIS INSTALLATION IS LOCATED TWO NM NORTHWEST OF HAI PHONG RAILROAD STATION, CLASSIFICATION YARD AND SHOPS

3. BACKGROUND:

PRIOR TO THE FIRST U.S. AIR STRIKE AGAINST THE HAI PHONG PETROLEUM PRODUCTS STORAGE ON THIS FACILITY CONSISTED OF THIRTY ABOVEGROUND CYLINDRICAL PETROLEUM STORAGE TANKS OF VARYING SIZES AND CAPACITIES AND FIVE SMALL HORIZONTAL SERVICE TANKS. THE TOTAL PRE-STRIKE STORAGE CAPACITY OF THE INSTALLATION WAS ASSESSED AT 47,925 METRIC TONS.

NGA Review Complete

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Collateral Support

Approved For Release 2006/02/27: CIA-RDP79-00849A000700040015-7

25X1

25X1

Approved For Release 2006/02/27 · CIA-RD CONFIDENTIAL 00/40015-7

25X1

25X1

25X1

(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

REFERENCE: BLUE SPRINGS

5X1

5X1

ATTACHMENT TO L-2885 15 MARCH 1967 PAGE 2

PHOTOGRAPHY OF EARLY

REVEALED A NEWLY

IDENTIFIED PROBABLE UNDERGROUND STORAGE AREA WITHIN THIS FACILITY LOCATED ON THE SOUTH BANK OF THE CUA CAM (DISTRIBUTARY) BETWEEN THE MIDDLE AND EASTERN PIERS. THE

AREA CONTAINED AT LEAST TWENTY BUNKERED TANKS.

THE STRIKE OF AND SUBSEQUENT AIR

STRIKES HAVE RENDERED THE FACILITY UNSERVICEABLE FOR

CONVENTIONAL ABOVEGROUND STORAGE AND REDUCED THE TOTAL

STORAGE CAPACITY TO APPROXIMATELY 481 METRIC TONS, ALL

OF WHICH IS LOCATED IN THE BUNKERED STORAGE AREAS.

4. MISSION READOUT:

BLUE SPRINGS

REVEALS THAT

TWENTY-EIGHT OF THE THIRTY ABOVEGROUND TANKS ARE
DESTROYED OR DISMANTLED AND THE TWO LARGER ABOVEGROUND
TANKS WHICH REMAIN ARE SEVERELY DAMAGED AND PRESENTLY
UNUSABLE FOR PETROLEUM STORAGE. OF THE FIVE SMALL
SERVICE TANKS, FOUR ARE DESTROYED AND ONE IS POSSIBLY
DAMAGED. THE MAJORITY OF THE BUILDINGS IN THE FACILITY,
INCLUDING THE WEST PUMPHOUSE AREA, ARE EITHER DESTROYED
OR SEVERELY DAMAGED; THE EAST PUMPHOUSE AREA IS ONLY
SUPERFICIALLY DAMAGED.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Collateral Support

Approved For Release 2006/02/27 : CIA-RDP79-00849A000700040015-7

25X1

(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

REFERENCE: BLUE SPRINGS

X1

ATTACHMENT TO L-2885 15 MARCH 1967 PAGE 3

REMAINING USABLE STORAGE IS CONFINED TO THE

UNDERGROUND STORAGE AREAS NEAR THE SOUTH BANK OF THE

CUA CAM. THE AREA BETWEEN THE MIDDLE AND EASTERN PIERS

CONTAINS TWELVE LARGE (25 METRIC TON) BUNKERED TANKS,

ONE UNBURIED 25 METRIC TON TANK, AND EIGHT STANDARD

(12 METRIC TON) BUNKERED TANKS. AT LEAST FIVE ADDITIONAL

12 METRIC TON BUNKERED TANKS ARE LOCATED NEAR THE

WESTERN EDGE OF THE FACILITY.

SEVERAL OTHER BUNKERED TANKS OF SMALL CAPACITY
ARE POSSIBLY LOCATED WITHIN THE FACILITY; HOWEVER,
THESE WOULD NOT SIGNIFICANTLY CHANGE THE STORAGE
CAPACITY.


AT LEAST SIXTEEN RAIL TANK CARS ARE OBSERVED ON THE RAIL SIDINGS SOUTH OF THE FACILITY.

BLUE SPRINGS	

25X1

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Collateral Support Division, NPIC.





25X1